



photo 1: A two track ranch road runs thru the location.



photo 2: South side of the location facing northwest. The vegetation has not established along the west side of the location. It appears this area was recently drill seeded.



photo 3: West side of the location facing east.



photo 4: Facing north at the northwest side of the location. This area appears to have recently been drill seeded.



photo 5: Facing south along the east side of the location. Vegetation is well established in this area.



photo 6: Facing east toward the surrounding undisturbed vegetation.