

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2017

Submitted Date:

02/23/2017

Document Number:

674901514**FIELD INSPECTION FORM**Loc ID 325249 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|------------------------------------|---------------------------------------|
| Walker, Crystal | | Crystal.Walker@conocophillips.com | All Inspections |
| Brock, Christine | | Christine.Brock@conocophillips.com | |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Busse, Dollie | 505-324-6104 | dollie.l.bussie@conocophillips.com | SW Inspection Reports |
| Prasanna, Sonu | | Sonu.Prasanna@conocophillips.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 214397 | WELL | PR | 03/30/1998 | GW | 067-05815 | ALLISON UNIT 25 | EI |

General Comment:

On February 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Burlington Resources Allison Unit #25. For the most recent field inspection report for this facility, please refer to document #674601112.

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Location sign mounted near location entrance. | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Label and placard on perimeter fencing. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | TANK BATTERY | | |
| Comment: | Perimeter fencing around secondary containment berm. | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|------------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | Pipeline risers. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|----------------|---|----------|----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | Open Top | | 37.002628,-107.548474 |
| Comment: | Tank in metal cellar. Expanded metal cover. | | | | |

| | | | |
|---------------------------|----------|---------------------|---------------------|
| Corrective Action: | | Date: | |
| Paint | | | |
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) 120 bbl. | | | |
| Other (Type) | | | |
| Berms | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) |
| Metal | Adequate | Walls Sufficient | Base Sufficient |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 214397 | Type: | WELL | API Number: | 067-05815 | Status: | PR | Insp. Status: | EI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Culverts | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|---------|------------|
| On February 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Burlington Resources Allison Unit #25. For the most recent field inspection report for this facility, please refer to document #674601112. | hughesj | 02/23/2017 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 674901515 | Open topped PW AST within metal cellar. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4083022 |
| 674901516 | BR Allison Unit #25 well head. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4083023 |