

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/21/2017

Document Number:

674901465**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325156 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26625  
Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
Address: 12225 GREENVILLE AVE STE 950  
City: DALLAS State: TX Zip: 75243-

**Findings:**

- 7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214148	WELL	PR	05/19/2003	GW	067-05464	FORD-OLSON UNIT 1	EI

**General Comment:**

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Ford Olson #1. For the most recent field inspection report of this facility, please refer to document #680600825.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing location sign near wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 3	Comment: SW rig anchor marker was not found.			
Type: Gas Meter Run	# 1	Comment:			
Type: Horizontal Separator	# 1	Comment:			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	STEEL AST		37.115070,-107.718273
Comment:	Tank is rusted near base. Expanded metal top is not painted.				
Corrective Action:				Date:	

**Paint**

Condition	Inadequate
Other (Content)	
Other (Capacity)	20 bbl.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 214148 Type: WELL API Number: 067-05464 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Sediment Traps	Pass	Ditches	Pass			
Rip Rap	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Ford Olson #1. For the most recent field inspection report of this facility, please refer to document #680600825.	hughesj	02/21/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401215604	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080502">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080502</a>
674901466	Wattles along run off control ditch.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080498">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080498</a>
674901467	Wattles near sediment trap.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080499">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080499</a>
674901468	20 bbl. open topped PW AST.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4080500</a>