

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo from prior inspection for comparison



Photo 1: Weeds controlled, shed removed.

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo 2: Stained soil at wellhead, no bradenhead plumbed to surface.



Photo 3: Stained soil at risers near manifold

Inspection Photos
Location Name: Sidney Strear 1
API: 05-123-07883



Photo 4: Stained soil at valve around tank



Photo 5: Weeds around meter run. (Battery is Kerr-McGee)