

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/22/2017

Document Number:

674901478

### FIELD INSPECTION FORM

Loc ID 333774 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26625  
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
 Address: 12225 GREENVILLE AVE STE 950  
 City: DALLAS State: TX Zip: 75243-

**Findings:**

- 9 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">SW Inspection Reports</a>
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290036	WELL	PR	04/08/2011	GW	067-09348	IGW 119	EI

**General Comment:**

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company IGW #119. For the most recent field inspection report of this facility, please refer to document #674601242.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			
Lube Oil	Pump Jack	<= 1 bbl			
Comment:	Impacted material beneath prime mover.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.			Date:	03/22/2017

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	PUMP JACK		
Comment:	Guard fencing.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Fencing around perimeter of secondary containment berm.		
Corrective Action:		Date:	

**Equipment:**

Type	#		corrective date
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:	Concrete pad and soil underneath prime mover are stained.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 60		Date: 03/22/2017
Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		37.120710,-107.763216

Comment:		
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 290036 Type: WELL API Number: 067-09348 Status: PR Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_  
Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

\_\_\_\_\_

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company IGW #119. For the most recent field inspection report of this facility, please refer to document #674601242.</a>	hughesj	02/22/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401216676	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081633">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081633</a>
674901479	Impacted material beneath prime mover.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081628">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081628</a>
674901480	Stained concrete pad and gravel.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081629</a>