

Location

Lease Road:

Type Access

comment: Muddy at time of inspection

Corrective ActionL

Date:

Overall Good:

Signs/Marker:

Type WELLHEAD

Comment:

Corrective Action:

Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 210562 Type: WELL API Number: 045-06318 Status: PR Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Form 4 Doc#400865795 on file for continued temporarily abandoned status. Passed MIT on 1/8/15.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Location was muddy and rutted from seasonal conditions at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401216679	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081635
675203855	Calf Canyon Fed 34-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4081630