

Inspection Photos

02/28/2017

Operator: Foundation Energy #10112

Location ID: 330865

Inspection Doc. Number: 682501708

Weld County, CO

NENW Section 36 T6N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 1: Photo taken southwest corner of the tank battery, on the southeast end of the location facing north. Photo shows berms remain low, insufficient and unrepaired.



Photo 2: Photo taken southwest corner of the tank battery, on the southeast end of the location facing east. Photo shows berms remain low, insufficient and unrepaired.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 3: Photo taken from the southern tank, on the southeast end of the location. Photo show placard labels are still missing information such as name of operator, operator's emergency contact telephone number, and tank capacity.



Photo 4: Photo taken from the northern tank, on the southeast end of the location. Photo show placard labels are still missing information such as name of operator, operator's emergency contact telephone number, and tank capacity.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 5: Photo of sign at tank battery. Photo shows sign remains deteriorated in such a manner that the operator emergency contact information is illegible.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 6: Photo taken from location. Photo shows high abundance of *Tribulus terrestris* (Puncturevine, goat-head). This is a Colorado State noxious weed. Weeds need to be managed and removed.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 7: Photo taken from the south end of the location, facing north. Photo shows erosion degradation on the location. Photo shows stormwater and sediment control BMPs have not been installed.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 10: Photo taken from the south end of the location, facing north. Photo shows erosion degradation on the location. Photo shows stormwater and sediment control BMPs have not been installed. 6 foot measuring stick for reference.



Photo 11: Photo taken from the south end of the location. Photo shows erosion degradation on the location. Photo shows stormwater and sediment control BMPs have not been installed. 6 foot measuring stick for reference.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 12: Photo taken from the southwest corner of the location, facing east. Photo vegetation over the interim area. Note vegetation is predominantly undesirable weedy plant species. Very little evidence of perennial vegetation establishment found.



Photo 13: Photo taken from the southwest corner of the location, facing north. Photo vegetation over the interim area. Note vegetation is predominantly undesirable weedy plant species. Very little evidence of perennial vegetation establishment found.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 14: Photo taken from the interim area of the location. Photo shows vegetation over the interim area. Note vegetation is predominantly undesirable weedy plant species. Very little evidence of perennial vegetation establishment found. 6 foot measuring stick for reference.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 15: Photo taken from the northwest end of the location. Photo shows square iron tubing has not been removed or properly stored from location.



Photo 16: Photo taken from the northwest end of the location. Photo shows square iron tubing has not been removed or properly stored from location.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 17: Photo taken from the north end of the location, facing north. Photo shows erosion degradation on the location. Photo shows stormwater and sediment control BMPs have not been installed. 6 foot measuring stick for reference.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 18: Photo taken from northeast end of the location at skim pit. Inspection Doc. #684901990 required operator to Submit form 15 eform pit report (10 days); No form 15 found in well or location records for a produced water skim pit.

Inspection Photos
Operator: Foundation Energy #10112
Location ID: 330865



Photo 19: Photo taken at well. Photo shows sign remains missing from wellhead.