

Stormwater Inspection

February 27, 2017

Operator: CONOCO PHILLIPS COMPANY - # 19160

API: 005-07177

Arapahoe County, CO

SENW Section 32 T4S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Tebo 32 #2
API: 05-005-07177



Photo 1. Photo taken from the northeast location, facing East. Wattles have been replaced along the northeast production area and interim areas. Wattles do not appear to be trenched or backfilled along this portion. Stormwater runoff might undermine the wattle and not properly function.



Photo 2. Photo taken from the northeast location, facing North. Wattles have been replaced along the northeast production area and interim areas. Appears gravel has been built up in front of wattle to prevent stormwater runoff from undermining the wattles. Wattles have been overlapped at the joints.

Inspection Photos
Location Name: Tebo 32 #2
API: 05-005-07177



Photo 3. Photo taken from the northeast location along the current interim area, facing North. Gully erosion has been repaired in addition to installing wattles.