

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/27/2017

Submitted Date:

03/01/2017

Document Number:

682401832

FIELD INSPECTION FORM

Loc ID 426630 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 19160
Name of Operator: CONOCO PHILLIPS COMPANY
Address: P O BOX 2197
City: HOUSTON State: TX Zip: 77252-

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Farrell, Larissa		Larissa.L.Farrell@conocophillips.com	All Inspections
Prasanna, Sonu		Sonu.Prasanna@conocophillips.com	All Inspections
Trujillo, Aaron		aaron.trujillo@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
426629	WELL	AC	04/21/2014	OBW	005-07177	Tebo 32 2	AC

General Comment:

This is a follow up stormwater inspection in response to Form 42 Document #401217027 received on 2/22/2017 stating corrective actions from FIR Document #682501637 have been preformed. Any corrective actions from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 426629 Type: WELL API Number: 005-07177 Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					

Comment: [FIR Document #682501637](#) required to install or repair required BMPs along the northeast production area and interim area where gully erosion was forming. Corrective actions have been performed along the described area. It should be noted that portions of the wattle did not appear to be trenched or backfilled. Stormwater runoff might undermine the wattle and not properly function. BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to attached inspection photos in Document #682401833.	binschusc	03/01/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401833	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4088263