

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2017

Submitted Date:

03/01/2017

Document Number:

666802952

FIELD INSPECTION FORM

Loc ID 335439 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 10 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrllc.com	Sr. EH&S
Axelson, Aaron	970-230-0926	aaxelson@vnrllc.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277735	WELL	PR	11/08/2005	GW	045-10762	LOUTHAN 41D-34-692	PR
277738	WELL	PR	12/01/2005	GW	045-10761	LOUTHAN 31B-34-692	PR
277739	WELL	PR	12/06/2005	GW	045-10760	LOUTHAN 41B-34-692	PR
277759	WELL	PR	10/24/2005	GW	045-10763	LOUTHAN 31D-34-692	PR

General Comment:

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	100 BBLs	STEEL AST				
Comment:		Centralized battery					
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	3	200 BBLs	STEEL AST		39.490112,-107.647322		
Comment:							
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Insufficient	Adequate			
Comment:							
Corrective Action:				Date:			
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:				Date:			
Flaring:							
Type							
Comment:							
Corrective Action:				Date:			

Inspected Facilities									
Facility ID:	<u>277735</u>	Type:	<u>WELL</u>	API Number:	<u>045-10762</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>277738</u>	Type:	<u>WELL</u>	API Number:	<u>045-10761</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>277739</u>	Type:	<u>WELL</u>	API Number:	<u>045-10760</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			
Facility ID:	<u>277759</u>	Type:	<u>WELL</u>	API Number:	<u>045-10763</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:						Date:			

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT