

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/17/2017

Submitted Date:

02/23/2017

Document Number:

674901495

### FIELD INSPECTION FORM

Loc ID 326371 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26625  
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
 Address: 12225 GREENVILLE AVE STE 950  
 City: DALLAS State: TX Zip: 75243-

**Findings:**

- 4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Lindeman, Terry	(505) 632-3476 Ext 210	tlindeman@elmridge.net	
Archuleta, Amy		aarchuleta@elmridge.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216325	WELL	PR	01/11/1994	GW	067-07931	JULIAN GAS UNIT 2	EI

**General Comment:**

On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Julian GU #2. For the most recent field inspection report of this facility, please refer to document #674600119.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Vertical Heated Separator	# 1		corrective date
Comment:	Combination separator/meter run.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		37.105707,-107.762539
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 216325 Type: WELL API Number: 067-07931 Status: PR Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">On February 17, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Company Julian GU #2. For the most recent field inspection report of this facility, please refer to document #674600119.</a>	hughesj	02/23/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401217607	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082631</a>
674901496	300 bbl. AST.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082629">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082629</a>
674901497	Combo meter run/separator.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082630">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082630</a>