

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/16/2017

Submitted Date:

02/23/2017

Document Number:

674901511

FIELD INSPECTION FORM

Loc ID 326488 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 26580
 Name of Operator: BURLINGTON RESOURCES OIL & GAS LP
 Address: PO BOX 4289
 City: FARMINGTON State: NM Zip: 87499

Findings:

- 11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Brock, Christine		Christine.Brock@conocophillips.com	
Prasanna, Sonu		Sonu.Prasanna@conocophillips.com	
Fischer, Alex		alex.fischer@state.co.us	
Walker, Crystal		Crystal.Walker@conocophillips.com	All Inspections
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89082	WELL	PR	07/09/1999	GW	067-08186	ALLISON UNIT 25M	EI

General Comment:

On February 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Burlington Resources Allison Unit #25M. For the most recent field inspection report of this facility, please refer to document #674601110.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Sign mounted to perimeter fencing for PW vessel.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Location sign mounted to fence near PW vessel.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	_____
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	TANK BATTERY		
Comment:	Perimeter fencing around PW vessel.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical injection system.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.003167,-107.540680
Comment:	Expanded metal cover.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	120 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 89082 Type: WELL API Number: 067-08186 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chemical tank.

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On February 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Burlington Resources Allison Unit #25M. For the most recent field inspection report of this facility, please refer to document #674601110.	hughesj	02/23/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401217944	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082958
674901512	BR Allison Unit #25M well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082956
674901513	Chemical injection system with secondary containment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4082957