

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2017

Submitted Date:

02/23/2017

Document Number:

674901514**FIELD INSPECTION FORM**

Loc ID 325249	Inspector Name: Hughes, Jim	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>26580</u> Name of Operator: <u>BURLINGTON RESOURCES OIL & GAS LP</u> Address: <u>PO BOX 4289</u> City: <u>FARMINGTON</u> State: <u>NM</u> Zip: <u>87499</u>				

Contact Information:

Contact Name	Phone	Email	Comment
Walker, Crystal		Crystal.Walker@conocophillips.com	All Inspections
Brock, Christine		Christine.Brock@conocophillips.com	
Busse, Dollie	505-324-6104	dollie.l.bussie@conocophillips.com	SW Inspection Reports
Prasanna, Sonu		Sonu.Prasanna@conocophillips.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214397	WELL	PR	03/30/1998	GW	067-05815	ALLISON UNIT 25	EI

General Comment:

On February 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Burlington Resources Allison Unit #25. For the most recent field inspection report for this facility, please refer to document #674601112.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign mounted near location entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Label and placard on perimeter fencing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Perimeter fencing around secondary containment berm.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Pipeline risers.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		37.002628,-107.548474	
Comment:	Tank in metal cellar. Expanded metal cover.					

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity) 120 bbl.			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Metal	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On February 16, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Burlington Resources Allison Unit #25. For the most recent field inspection report for this facility, please refer to document #674601112.	hughesj	02/23/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401218029	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4083024
674901515	Open topped PW AST within metal cellar.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4083022
674901516	BR Allison Unit #25 well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4083023