

Inspection Photos
Location Name: Carl R. Deepe C 1
API: 05-123-07871



Photo 1: Stained soil at wellhead



Photo 2: Weeds in tank battery berm

Inspection Photos
Location Name: Carl R. Deepe C 1
API: 05-123-07871



Photo 1: Stained soil at manifold



Photo 2: Stained soil in horizontal separator house

Inspection Photos
Location Name: Carl R. Deepe C 1
API: 05-123-07871



Photo 1: Placard on battery sign is faded, no visible emergency number