



Photo#1: Overview of Location to North

February 16, 2017

Inspection Photos: Chevron PA Sharpes McLaughlin 1-32
API#103-01074

Photo#2:

Pipe Risers and Concrete South down slope from PA Marker

Photo#3:



Photo#4:

Erosion occurring North & South of Pipes /Risers



Photo#5:



Photo#6:

Concrete Pad Remnant at East edge of Loc. Red Arrow indicates 2cd Pad Remnant. Black Arrow indicates lower Facilities Site. Insert is close up of 2cd pad remnant.



February 16, 2017

Inspection Photos: Chevron PA Sharpes McLaughlin 1-32
API#103-01074

Photo#7:

Lower Unknown Facilities showing 1st open Pipe 5 ft SE of Stubbed Pipe. 4" open pipe; 14" from top of pipe to TD where it feels as if pipe heads to West



Photo#8:




Photo#9:

2cd Pipe 19 ft South of 1st Pipe; 4" open pipe; 14" from top of pipe to TD where it feels as if pipe heads to West.



Photo#10:





Photo#11: View N to S of stubbed pipe; With arrows indicating open Pipe riser positions.

Inspection Photos: Chevron PA Sharpes McLaughlin 1-32
API#103-01074

February 16, 2017

Photo#12:

Flow -lines piping between two Sites; view from SE to NW.



Photo#13:



February 16, 2017

Inspection Photos: Chevron PA Sharpes McLaughlin 1-32
API#103-01074

Photo#14:
Lines / Pipe exiting base of Lower Facilities site.



February 16, 2017

Inspection Photos: Chevron PA Sharpes McLaughlin 1-32
API#103-01074