

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2017

Submitted Date:

03/03/2017

Document Number:

681700300**FIELD INSPECTION FORM**Loc ID 333070 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH CO ADBA ENERGY SEARCH COAddress: PO BOX 1896City: EDWARDS State: CO Zip: 81632**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Marisco, Joe	(303) 320-6546	joemarisco@yahoo.com	
Robuck, Don		buckaroo51@msn.com	ALL Inspections
Robuck, Brett	(303)345-7200	RPLLC@msn.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202001	WELL	PR	02/18/2015	OW	001-07405	NORTH COLORADO BOULEVARD 4	EI

General Comment:

COGCC Environmental Inspection of wellhead only. Corrective actions from 9/3/2015 Field Inspection Report #668703473 remain unresolved. Where corrective actions listed on previous inspection reports have not been addressed, corrective action dates remain unchanged.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign was not secured to fence (see photo)		
Corrective Action:	Immediately install sign to comply with Rule 210.b	Date:	10/03/2015

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	WEEDS		
Comment:	Site-wide uncontrolled weeds (see photo).		
Corrective Action:	Immediately comply with Rule 603.f using the Rule 603.f guidance document for further details	Date:	10/03/2015

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Localized, oil-stained soil at wellhead and propane tank.			
Corrective Action:	Remove and properly dispose of stained soil.			Date: 04/03/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chain link fence is damaged (see photos).		
Corrective Action:	Repair fence as part of routine maintenance operations.	Date:	04/03/2017

Equipment:			corrective date
Type: Other	# 1		
Comment:	Steel risers at wellhead are open to atmosphere (see photos).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 04/03/2017

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202001 Type: WELL API Number: 001-07405 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681700310	wellhead sign in tall grass	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090104
681700311	uncontrolled weeds at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090105
681700312	localized, oil-stained soil at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090106
681700313	open riser south of wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090107
681700314	open riser north of wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090108
681700315	damage on east side of fence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090109
681700316	damage on north side of fence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090110