

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2017

Submitted Date:

02/28/2017

Document Number:

672500421**FIELD INSPECTION FORM**Loc ID 306515 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------|
| , | | cogccinspection@pdce.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 289324 | WELL | PR | 03/01/2015 | GW | 123-24818 | DALTON 24-24 | PR |

General Comment:

Location

| | | | |
|--------------------|-----------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | 2 TRACK AG LAND | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | WIRE | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | AG PANEL | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | WIRE | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | ECD AG PANEL | | |
| Corrective Action: | | Date: | |

| | | | | |
|-----------------------------------|-----|--|--|-----------------|
| Equipment: | | | | corrective date |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Emission Control Device | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Bird Protectors | # 2 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Pig Station | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|----------|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 100 BBLs | PBV FIBERGLASS | | 40.553820,-104.727360 |
| Comment: | ANCHORED | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 300 BBLs | STEEL AST | | 40.553820,-104.727360 |
| Comment: | ANCHORED | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|--------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 289324 | Type: | WELL | API Number: | 123-24818 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | PLUMBED TO SURFACE | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | | | | | |
| Culverts | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| CORRECTIVE ACTIONS FROM INSPECTION DOC#673800967 HAVE BEEN COMPLETED TO COMPLY WITH COGCC RULES | gomezj | 02/28/2017 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401221201 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4086719 |