

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401226699

Date Received:

03/07/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Prescott, Lorne	(970) 812-5311	lprescott@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680101555

Inspection Date: 03/03/2017

FIR Submit Date: 03/05/2017

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1401 SEVENTEENTH STREET #1400

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449070

Location Name: Gunderson Number: 20-03 Pad County: _____

Qtrqtr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.266756 Longitude: -107.795281

FACILITY - API Number: 05-077-00 Facility ID: 449070

Facility Name: Gunderson Number: 20-03 Pad

Qtrqtr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.266756 Longitude: -107.795281

CORRECTIVE ACTIONS:

2 CA# 66370

Corrective Action: Ditches, Appropriate BMPs need to be installed along Sides of Access Road.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/07/2017

Operator Comment: As indicated in the photographs, construction activity and earth moving with heavy equipment was occurring at the time of this inspection. As such, BMP installation was evolving and ongoing. Photos also demonstrate compaction and roughening was taking place at the time of the inspection. Because this inspection took place at the peak of daily construction activities, many (if not all) of the concerns identified by this inspection were resolved by day's end. Appropriate BMPs have been implemented and/or installed.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 66371

Corrective Action: Wattles, Appropriate BMPs need to be installed along Soil piled off & along Access Road on Fill side and all along North edge of Location where Topsoil has been piled close to LOD.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/07/2017

Operator Comment: As indicated in the photographs, construction activity and earth moving with heavy equipment was occurring at the time of this inspection. As such, BMP installation was evolving and ongoing. Photos also demonstrate compaction and roughening was taking place at the time of the inspection. Because this inspection took place at the peak of daily construction activities, many (if not all) of the concerns identified by this inspection were resolved by day's end. Appropriate BMPs have been implemented and/or installed.

COGCC Decision: _____

COGCC Representative: _____

4 CA# 66372

Corrective Action: Roughening, Appropriate BMPs need to be installed along Soil piled off & along Access Road on Fill side and all along North edge of Location where Topsoil has been piled close to LOD.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/07/2017

Operator Comment: As indicated in the photographs, construction activity, earth moving with heavy equipment and BMP implementation was occurring at the time of this inspection. As such, BMP installation was evolving and ongoing. Photos also demonstrate compaction and roughening was taking place at the time of the inspection. Because this inspection took place at the peak of daily construction activities, many (if not all) of the concerns identified by this inspection were resolved by day's end. Appropriate BMPs have been implemented and/or installed.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: As indicated in the photographs, construction activity and earth moving with heavy equipment was occurring at the time of this inspection. As such, BMP installation was evolving and ongoing. Photos also demonstrate compaction and roughening was taking place at the time of the inspection. Because this inspection took place at the peak of daily construction activities, many (if not all) of the concerns identified by this inspection were resolved by day's end. Appropriate BMPs have been implemented and/or installed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: _____

Title: Reg & Enviro Compliance

Date: 3/7/2017 8:28:54 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

401226728 Inspection photos

Total Attach: 1 Files