

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G 4**  
**API: 05-123-08958**



**Photo from prior inspection for comparison purposes**



**Photo 1: Faded sign**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G 4**  
**API: 05-123-08958**



**Photo from prior inspection for comparison purposes**



**Photo 2: Stained soil at tank loadout**



**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G 4**  
**API: 05-123-08958**



**Photo from prior inspection for comparison purposes**



**Photo 3: Stained soil at valve**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G 4**  
**API: 05-123-08958**



**Photo from prior inspection for comparison purposes**



**Photo 4: Stained soil near battery, to south**



**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G 4**  
**API: 05-123-08958**



**Photo 5: Stained soil beneath loadout**



**Photo 6: Stained soil at tank**

**Inspection Photos**  
**Location Name: UPRR 42 Pan Am G 4**  
**API: 05-123-08958**



**Photo 7: Stained soil at separator**



**Photo 8: Stained soil, weeds at produced water tank on east side**