

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/01/2017

Submitted Date:

03/08/2017

Document Number:

674603201**FIELD INSPECTION FORM**
 Loc ID 330885 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
,		cogccinspection@pdce.com	
Hazard, Ellice		ellice.hazard@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256243	WELL	PR	05/14/2007	GW	123-19823	SLW RANCH 34-7	EG

General Comment:

COGCC Integrity Inspection (flowline) performed on March 1st, 2017 in response to initial form 19 spill report Doc #401221401 received on 03/01/2017 that outlines: PDC Energy discovered a reportable produced water release on the SLW Ranch 24, 34, 44-7 during flowline integrity testing. Upon discovery the facility was immediately shut in and vault bottomed out. The details of observations made during this field inspection are available in the flowline section of this report. Photo's have been uploaded and can be accessed via link(s) at the end of this report.

Inspected FacilitiesFacility ID: 256243 Type: WELL API Number: 123-19823 Status: PR Insp. Status: EG**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: Size: Material:
 Variance: Age: 20+ Yrs Contents: Produced Water

Integrity Summary

Failures: Spills: Yes Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: There were no PDC personnel on location at the time of this field inspection. Based on email communications with Zack Liesenfeld on 3/2/2017, both remediation and flowline repair work is going to be scheduled in the near future. COGCC Integrity staff will be notified once scheduling has been completed. Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of all flowline repairs completed (on supplemental form 19); perform flowline pressure testing to verify integrity of all new flowlines and repairs completed (retain chart & data) prior to returning flowlines/ dump lines to service.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674603211	Wellhead and Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092956
674603212	Battery on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092957