

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2017

Submitted Date:

03/06/2017

Document Number:

685302316**FIELD INSPECTION FORM**Loc ID 326386 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone        | Email               | Comment                               |
|------------------|--------------|---------------------|---------------------------------------|
| Inspections, All |              | SanJuanCOGCC@bp.com | <a href="#">SW Inspection Reports</a> |
| Beebe, Sabre     | 970-375-7530 | Sabre.Beebe@bp.com  | <a href="#">SW Inspection Reports</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 216350      | WELL | PR     | 10/30/2014  | GW         | 067-07956 | WARREN DAVIS C 1     | PR          |
| 428059      | WELL | XX     | 03/06/2012  | LO         | 067-09883 | Davis, Warren GU C 3 | XX          |

**General Comment:**

See link at end of report for path to downloadable pictures. Inspection report contains comments. See Good Housekeeping section of report for additional comments.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | DEBRIS  |       |  |
| Comment:           | Furniture and trash were recently dumped off the E side of location. Vehicle tracks were fresh. Clean up and remove debris. |       |  |
| Corrective Action: |   | Date: |  |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |       |
|--------------------|---|----------|-----------|---------|--------|-------|
| PRODUCED WATER     | 1 | OTHER    | PBV STEEL |         | ,      |       |
| Comment:           |   |          |           |         |        |       |
| Corrective Action: |   |          |           |         |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 95 BBLS  |  |
| Other (Type)     |          |  |

**Berms**

| Type               | Capacity                     | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|------------------------------|---------------------|---------------------|-------------|
| Earth              | Adequate                     | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | Corrective action completed. |                     |                     |             |
| Corrective Action: |                              |                     |                     |             |
|                    |                              |                     | Date:               |             |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>216350</u> | Type: <u>WELL</u> | API Number: <u>067-07956</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>428059</u> | Type: <u>WELL</u> | API Number: <u>067-09883</u> | Status: <u>XX</u> | Insp. Status: <u>XX</u> |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description              | URL   |
|--------------|--------------------------|---|
| 685302321    | Produced water tank.     | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092974">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092974</a> |
| 685302322    | Close up of berm repair. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092975</a> |
| 685302323    | Dumped debris.           | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092976">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092976</a> |