

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/01/2017

Submitted Date:

03/01/2017

Document Number:

672500433

FIELD INSPECTION FORM

Loc ID 335697 Inspector Name: Gomez, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

12 Number of Comments
2 Number of Corrective Actions

Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275610	WELL	PR	07/14/2009	GW	001-09527	STANDLEY 5-2	PR
275611	WELL	PR	10/07/2011	GW	001-09528	STANDLEY 6-2	PR
275817	WELL	PR	10/07/2011	GW	001-09531	STANDLEY 8-3	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG PANEL		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Plunger Lift	# 3	

Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		39.992020,-104.978760
Comment:	268 BBL				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	HOLES IN WALL ON EAST END OF BERM WALL WALLS APPEAR TO BE LOW FOR CONTAINMENT SEE ATTACHED PHOTOS			
Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."			Date: 03/20/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		39.992020,-104.978760
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	HOLES IN WALL ON EAST END OF BERM WALL WALLS APPEAR TO BE LOW FOR CONTAINMENT SEE ATTACHED PHOTOS				
Corrective Action:	"Location is within a designated setback location, repair or install berms or other secondary containment devices per Rule 604.c.(2)G."			Date:	03/20/2017

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: <u>275610</u>	Type: <u>WELL</u>	API Number: <u>001-09527</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>275611</u>	Type: <u>WELL</u>	API Number: <u>001-09528</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
Facility ID: <u>275817</u>	Type: <u>WELL</u>	API Number: <u>001-09531</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>
BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>	Corrective Action: <input style="width: 100%;" type="text"/>		Date: <input style="width: 50%;" type="text"/>

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
		Culverts	Pass			
Compaction	Pass	Compaction	Pass	Vehicle Tracking	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401223100	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4088367
672500434	PHOTOS OF HOLES IN BERM WALL AND HIGHT OF WALLS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4088363