

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2017

Submitted Date:

03/02/2017

Document Number:

682401836**FIELD INSPECTION FORM**
 Loc ID 445139 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email                    | Comment |
|--------------|-------|--------------------------|---------|
| ,            |       | cogccinspection@pdce.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name               | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 445132      | WELL | XX     | 03/15/2016  |            | 123-42900 | Cecil's Kersey Farm 17K-334 | CI          |
| 445133      | WELL | XX     | 03/15/2016  |            | 123-42901 | Cecil's Kersey Farm 17K-204 | CI          |
| 445134      | WELL | XX     | 03/15/2016  |            | 123-42902 | Cecil's Kersey Farm 17B-212 | CI          |
| 445135      | WELL | XX     | 03/15/2016  |            | 123-42903 | Cecil's Kersey Farm 17K-402 | CI          |
| 445136      | WELL | DG     | 02/21/2017  |            | 123-42904 | Cecil's Kersey Farm 17K-404 | CI          |
| 445137      | WELL | XX     | 03/15/2016  |            | 123-42905 | Cecil's Kersey Farm 17K-332 | CI          |
| 445138      | WELL | XX     | 03/15/2016  |            | 123-42906 | Cecil's Kersey Farm 17B-302 | CI          |
| 445140      | WELL | XX     | 03/15/2016  |            | 123-42907 | Cecil's Kersey Farm 17K-232 | CI          |
| 448415      | WELL | XX     | 11/27/2016  |            | 123-43894 | Cecils Kersey Farm 17B-304  | CI          |
| 448416      | WELL | XX     | 11/27/2016  |            | 123-43895 | Cecils Kersey Farm 17B-214  | CI          |

**General Comment:**

This is a follow up desktop inspection in response to FIRR Document #401221912 received March 1, 2017 stating corrective actions from FIR Document #682401789 have been performed.

| Inspected Facilities       |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>445132</u> | Type: <u>WELL</u> | API Number: <u>123-42900</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445133</u> | Type: <u>WELL</u> | API Number: <u>123-42901</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445134</u> | Type: <u>WELL</u> | API Number: <u>123-42902</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445135</u> | Type: <u>WELL</u> | API Number: <u>123-42903</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445136</u> | Type: <u>WELL</u> | API Number: <u>123-42904</u> | Status: <u>DG</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445137</u> | Type: <u>WELL</u> | API Number: <u>123-42905</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445138</u> | Type: <u>WELL</u> | API Number: <u>123-42906</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>445140</u> | Type: <u>WELL</u> | API Number: <u>123-42907</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>448415</u> | Type: <u>WELL</u> | API Number: <u>123-43894</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>448416</u> | Type: <u>WELL</u> | API Number: <u>123-43895</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |

Comment: Based off photo documentation provided by the Operator, it appears that corrective actions from FIR Document #682401789 to install or repair required BMPs per Rule 1002.f. have been performed.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401224219    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4089435">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4089435</a> |