

Inspection Photos
Location Name: Ronald Grabrian Unit-True 1
API: 05-123-11439



Photo from prior inspection for comparison



Photo 1: Wellhead, looking SW. Weeds have been controlled

Inspection Photos
Location Name: Ronald Grabrian Unit-True 1
API: 05-123-11439



Photo from prior inspection for comparison



Photo 2: Berms at tank battery have been repaired.