

Inspection Photos
Location Name: Donald M Vynckier 2
API: 05-123-08941



Photo from prior inspection for comparison



Photo 1: Bradenhead plumbed to surface, stained soil remediated

Inspection Photos
Location Name: Donald M Vynckier 2
API: 05-123-08941



Photo from prior inspection for comparison



Photo 2: Fence has been repaired.