

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate.		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash in berm behind oil tank. See photo.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: <u>04/09/2017</u>

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Prime Mover	# 1			
Comment:	Electric motor.			
Corrective Action:				Date:
Pump Jack	# 1			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:	210 BBL oil storage tank, has leak on bolted seam towards bottom. See photo.				

Corrective Action:	Repair or replace tank to mitigate leak.	Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment: Weeds need to be mitigated in and on berm. See photo.				
Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.				Date: 04/09/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	FIBERGLASS AST		
Comment: Fiberglass produced water tank.					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Berm is shared with oil tank.				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 201484 Type: WELL API Number: 001-06887 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI, NOV-2015

Corrective Action: Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667601529	Battery view, weeds in and on berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4094842
667601530	Leak at bottom of oil storage tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4094843
667601531	Trash and weeds in and on berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4094844