

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2017

Submitted Date:

03/03/2017

Document Number:

681700300**FIELD INSPECTION FORM**Loc ID 333070 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 27635Name of Operator: ENERGY SEARCH CO ADDBA ENERGY SEARCH COAddress: PO BOX 1896City: EDWARDS State: CO Zip: 81632**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Robuck, Brett	(303)345-7200	RPLLC@msn.com	
Robuck, Don		buckaroo51@msn.com	<a href="#">ALL Inspections</a>
Marisco, Joe	(303) 320-6546	joemarisco@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202001	WELL	PR	02/18/2015	OW	001-07405	NORTH COLORADO BOULEVARD 4	EI

**General Comment:**

COGCC Environmental Inspection of wellhead only. Corrective actions from 9/3/2015 Field Inspection Report #668703473 remain unresolved. Where corrective actions listed on previous inspection reports have not been addressed, corrective action dates remain unchanged.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign was not secured to fence (see photo)		
Corrective Action:	Immediately install sign to comply with Rule 210.b	Date:	10/03/2015

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Site-wide uncontrolled weeds (see photo).		
Corrective Action:	Immediately comply with Rule 603.f using the Rule 603.f guidance document for further details	Date:	10/03/2015

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Crude Oil	WELLHEAD	<= 1 bbl		
Comment:	Localized, oil-stained soil at wellhead and propane tank.			
Corrective Action:	Remove and properly dispose of stained soil.			Date: 04/03/2017

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chain link fence is damaged (see photos).		
Corrective Action:	Repair fence as part of routine maintenance operations.	Date:	04/03/2017

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Steel risers at wellhead are open to atmosphere (see photos).		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 04/03/2017

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 202001    Type: WELL    API Number: 001-07405    Status: PR    Insp. Status: EI

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401224896	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090154">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090154</a>
681700310	wellhead sign in tall grass	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090104">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090104</a>
681700311	uncontrolled weeds at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090105">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090105</a>
681700312	localized, oil-stained soil at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090106">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090106</a>
681700313	open riser south of wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090107">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090107</a>
681700314	open riser north of wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090108">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090108</a>
681700315	damage on east side of fence	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090109">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090109</a>
681700316	damage on north side of fence	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090110">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090110</a>