

Location

Lease Road:			
Type	Main		
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	OK		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	BARBWIRE FENCE SE CORNER N39.55431 W-104.34869		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	#		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 201897 Type: WELL API Number: 001-07301 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
intermitter controller on wellhead DOCUMENT # 671105070, DATED 9/10/15, SOILED DIRT CLEANED UP TRASH HAULED OFF, WEEDS CONTROLLED, UNUSED EQUIPMENT REMOVED FROM LOCATION	montoyaj	03/03/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401225129	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4090390