

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2017

Submitted Date:

03/10/2017

Document Number:

679700374**FIELD INSPECTION FORM**
 Loc ID 326782 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 88380Name of Operator: TINDALL OPERATING COMPANYAddress: 12741 E CALEY STE 142City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Charles Davis		dnroilgas@hotmail.com	
Binschus, Chris		chris.binschus@state.co.us	
John Simms		jasimms9@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111640	PIT	AC			-	LIND 3	EI
111641	PIT	AC			-	LIND 5	EI
245869	WELL	PA	11/20/2015	OW	123-13664	LIND 3	EI

General Comment:[COGCC Environmental Inspection, followup to pit closure Remediation Project #9151](#)

Inspected Facilities									
Facility ID:	<u>111640</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>111641</u>	Type:	<u>PIT</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>245869</u>	Type:	<u>WELL</u>	API Number:	<u>123-13664</u>	Status:	<u>PA</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: ☐Pit ID: 111640Lat: 40.576724Long: -103.916698Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: ☐Oil Accumulation: ☐2+ feet Freeboard: ☐Comment: COGCC approved backfill of pit on 1/24/2017, pit has not been backfilled.Corrective Action: Backfill pit and submit supporting documentation requested in correspondence dated 1/24/2017. Reclaim site in accordance with Rule 1004.Date: 04/24/2017Type: Produced WaterLined: ☐Pit ID: 111641Lat: 40.576697Long: -103.916886Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition:

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	COGCC approved backfill of pit on 1/24/2017, pit has not been backfilled.	
Corrective Action	Backfill pit and submit supporting documentation requested in correspondence dated 1/24/2017. Reclaim site in accordance with Rule 1004.	
		Date: 04/24/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700375	Former skim pit and tank battery area looking N	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095278
679700376	Former pits and production area looking SW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095279
679700377	Wellpad not reclaimed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095280