

Inspection Photos
Location Name: Jack Berger A 4
API: 05-123-07717



Photo from prior inspection for comparison



Photo 1: Stained soil in separator house, SW corner

Inspection Photos
Location Name: Jack Berger A 4
API: 05-123-07717



Photo from prior inspection for comparison



Photo 2: Stained soil at valve

Inspection Photos
Location Name: Jack Berger A 4
API: 05-123-07717



Photo from prior inspection for comparison



Photo 3: Stained soil at risers

Inspection Photos
Location Name: Jack Berger A 4
API: 05-123-07717



Photo 4: Stained soil patches outside of berm



Photo 5: Stained soil at produced water loadout on S side.

Inspection Photos
Location Name: Jack Berger A 4
API: 05-123-07717



Photo 6: Stained soil in separator house, NE corner