

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2017

Submitted Date:

03/13/2017

Document Number:

685302371

FIELD INSPECTION FORM

Loc ID 313594 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 6720
Name of Operator: BAYLESS PRODUCER LLC* ROBERT L
Address: 621 17TH ST STE 2300
City: DENVER State: CO Zip: 80293

Findings:

- 12 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Rabinowitz, Daniel		drabinow@blm.gov	
Telecky, Barbara		btelecky@blm.gov	
Trujillo, Helen		notices@rlbayless.com	All inspections
Thomas, John	505-326-2659	jthomas@rlbayless.com	
Garrigues, Robert		rgarrigues@blm.gov	Tres Rios

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276380	WELL	PR	02/18/2006	OW	083-06617	NORTH MAIL TRAIL 1	PR

General Comment:

See link at end of report for path to downloadable pictures.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil - Corrective action complete.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Prime Mover	# 1		
Comment:	Corrective action completed.		
Corrective Action:		Date:	
Horizontal Heated Separator	# 1		
Comment:	Dump valve - Corrective action completed.		
Corrective Action:		Date:	
Emission Control Device	# 1		
Comment:	Combustor comment - Pilot visible.		
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment:	Wellhead leaking valve - Corrective action completed.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 276380 Type: WELL API Number: 083-06617 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.
Compaction	Pass	Gravel	Pass			

Comment: [Corrective action completed.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302400	Cleaned up tanl load out.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096845
685302401	Dump valve.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096846
685302402	Removed equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096847
685302403	Lube oil tank on spill prevention.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096848
685302404	Combustor.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096849
685302405	Exhaust pit.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096850