



**Photo 1:** View of the project area from the northeastern corner facing center.



**Photo 2:** View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is largely comprised of grasses such as James galleta (*Pleuraphis jamesii*).



**Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 4: View of the southern portion of the project area from the southeastern corner facing westward.**





**Photo 5: View of netting debris in the northeastern portion of the project area that needs to be removed.**



**Photo 6: View of cobble run-down in the southeastern portion of the project area. This and other stormwater controls appear to be functioning at this time.**