

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2017

Submitted Date:

03/06/2017

Document Number:

685302318**FIELD INSPECTION FORM**Loc ID 333541 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 87830Name of Operator: THOMPSON ENGINEERING & PRODUCTIONAddress: 7415 E MAINCity: FARMINGTON State: NM Zip: 87402**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Paul		paul@walsheng.net	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Thompson, John	/(970) 749-4238	john@walsheng.net	Consultant

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214097	WELL	PR	01/21/2016	GW	067-05404	BONDAD 33-9 34	PR

General Comment:

See link at end of report for path to downloadable pictures. Inspection report contains corrective action and comment. See Signs/Marker, Good Housekeeping, Equipment, and Tanks and Berms section of report for additional details.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Corrective action not completed. NFPA label has been replaced but the Capacity is faded and nearly unreadable.		
Corrective Action:	Install sign to comply with Rule 210.b and Rule 210.e Corrective action date remains the same to document days of non-compliance.	Date:	08/19/2016
Type	WELLHEAD		
Comment:	Sign is not currently attached to anything and is propped up against meter run house. Sign needs to be mounted in a conspicuous place. Noted in previous inspection.		
Corrective Action:	Install sign to comply with Rule 210.	Date:	05/06/2017

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Good Housekeeping:

Type	OTHER		
Comment:	Comment - Stained soil - Cleaned up.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Separator dump valve is continuously venting gas. Inspector on site when separator cycled and dumped to tank. Valve continued to vent after cycle. Seat needs to be cleaned or adjusted.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition. Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d	Date:	04/06/2017

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment:	Steel mesh top.					
Corrective Action:					Date:	

Paint

Condition	Adequate		
Other (Content)			

Other (Capacity) 94 BBLS						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment: Corrective action not completed.						
Corrective Action: Remove weeds and repair berms or install other secondary containment device to comply with Rule 605.a.(4). Corrective action date remains the same to document days of non-compliance.					Date:	07/21/2016
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		,	
Comment: Steel mesh top.						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 118 BBLS						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment: Corrective action not completed.						
Corrective Action: Remove weeds and repair berms or install other secondary containment device to comply with Rule 605.a.(4). Corrective action date remains the same to document days of non-compliance.					Date:	07/21/2016
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected FacilitiesFacility ID: 214097 Type: WELL API Number: 067-05404 Status: PR Insp. Status: PR**Producing Well**Comment: PR - Electronic well file reflects last reported production as June 2016.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401228097	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4093076
685302325	Well sign propped against meter house.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092978
685302326	Venting dump valve.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092979
685302327	Faded capacity on 94 BBL tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092980
685302328	Faded capacity on 118 BBL tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092981
685302329	Weeds around 118 BBL tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092982
685302332	Weeds around 94 BBL tank.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4092983