



photo 1: Facing south at the beginning of the access road.



photo 2: Facing southeast along the access road.



photo 3: The culverts installed along the road for the intermittent creek.



photo 4: This appears to be Plueless thistle (list B noxious weed) along the access road.



photo 5: Facing southeast along the access road.



photo 6: Rock rip/rap placed along the cut slope of the road.



photo 7: The access road continues past the location.



photo 8: Facing southeast toward the location.



photo 9: Facing southeast toward the location.



photo 10: Rock rip/rap placed along the diversion ditch.



photo 11: A diversion ditch is installed along the contour of the slope.



photo 12: Facing down along the northwest slope. The vegetation does not appear to be established.



photo 13: East side of the location facing west.



photo 14: Southwest side of the location facing northeast.