



photo 1: Facing northeast along the access road.



photo 2: Facing north along the access road.



photo 3: A gravel pile remains at the end of the access road at the location.



photo 4: Facing northeast toward the location.



photo 5: Facing east toward the location. There are rows of vegetation establishing.



photo 6: North side of the location facing south.



photo 9: Northeast side of the location facing southwest. Rock rip/rap is placed at the end of the diversion berm.



photo 10: East side of the location facing west.