

Construction and Stormwater Inspection

March 3, 2017

Operator: SYNERGY RESOURCES CORPORATION

Location ID: 449336

Weld County, CO

SESE Section 20 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Hood-Doles /37-20
Location ID: 449336



Photo 1. Photo taken from the entrance of location, facing Northwest. Culvert installed in conjunction with the existing roadside ditch.



Photo 2. Photo taken from the western location, facing North. Ditch and berm BMP installed around perimeter of location.

Inspection Photos
Location Name: Hood-Doles /37-20
Location ID: 449336



Photo 3. Photo taken from the northern location, facing East. Ditch and berm BMP installed around perimeter of location. Ensure berm BMPs are consistently compacted throughout location.



Photo 4. Photo taken from the eastern location, facing South. Ditch and berm BMP installed around perimeter of location.

Inspection Photos
Location Name: Hood-Doles /37-20
Location ID: 449336



Photo 5. Photo taken from the eastern location, facing South. Ditch and berm BMP installed around perimeter of location. Also, topsoil stockpile stored along eastern perimeter of location.



Photo 6. Photo taken from the southern location, facing West. Ditch and berm BMP installed around perimeter of location. Location with silt fence to the south is not part of this location or Operator.