

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/03/2017

Submitted Date:

03/15/2017

Document Number:

682401859

FIELD INSPECTION FORM

Loc ID: 447748 Inspector Name: Binschus, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10261
Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC
Address: 730 17TH ST STE 610
City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|---------------------|-----------------|
| Blyth, Tom | (303) 893-2503 | tblyth@bayswater.us | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 447880 | WELL | XX | 09/28/2016 | | 123-43651 | Ward V-20-19HN | CI |
| 447881 | WELL | XX | 09/28/2016 | | 123-43652 | Ward X-20-19HN | CI |
| 447882 | WELL | XX | 09/28/2016 | | 123-43653 | Ward U-20-19HN | CI |
| 447883 | WELL | XX | 09/28/2016 | | 123-43654 | Ward W-20-19HC | CI |
| 447884 | WELL | XX | 09/28/2016 | | 123-43655 | Ward M-20-19HN | CI |
| 447885 | WELL | XX | 09/28/2016 | | 123-43656 | Ward T-20-19HC | CI |
| 447886 | WELL | XX | 09/28/2016 | | 123-43657 | Ward O-20-19HN | CI |
| 447887 | WELL | XX | 09/28/2016 | | 123-43658 | Ward P-20-19HN | CI |
| 447888 | WELL | XX | 09/28/2016 | | 123-43659 | Ward Q-20-19HC | CI |
| 447889 | WELL | XX | 09/28/2016 | | 123-43660 | Ward S-20-19HN | CI |
| 447890 | WELL | XX | 09/28/2016 | | 123-43661 | Ward N-20-19HC | CI |
| 447891 | WELL | XX | 09/28/2016 | | 123-43662 | Ward R-20-19HN | CI |

General Comment:

This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401214175.

Location Construction

Location ID: 447748 CDP: _____

Comment: Topsoil salvaged, stored, and temporarily stabilized along the eastern perimeter of location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: An area of 3.53 acres was mapped on 3/3/2017 using a Trimble Juno 3B handheld device.

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment:

Corrective Action:

Date: _____

Stormwater:

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| DITCHES | Yes | | |

Comments: Erosion BMPs:

Other BMPs:

Corrective Action: _____ **Date:** _____

| SILT FENCES | Yes | | |
|-------------|-----|--|--|
| | | | |

Comments: Erosion BMPs:

Other BMPs:

Corrective Action: _____ **Date:** _____

| BERMS | Yes | | |
|-------|-----|--|--|
| | | | |

Comments: Erosion BMPs:

Other BMPs:

Corrective Action: _____ **Date:** _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

| | | | | |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>447880</u> | Type: <u>WELL</u> | API Number: <u>123-43651</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447881</u> | Type: <u>WELL</u> | API Number: <u>123-43652</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447882</u> | Type: <u>WELL</u> | API Number: <u>123-43653</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447883</u> | Type: <u>WELL</u> | API Number: <u>123-43654</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447884</u> | Type: <u>WELL</u> | API Number: <u>123-43655</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447885</u> | Type: <u>WELL</u> | API Number: <u>123-43656</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447886</u> | Type: <u>WELL</u> | API Number: <u>123-43657</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447887</u> | Type: <u>WELL</u> | API Number: <u>123-43658</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447888</u> | Type: <u>WELL</u> | API Number: <u>123-43659</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447889</u> | Type: <u>WELL</u> | API Number: <u>123-43660</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447890</u> | Type: <u>WELL</u> | API Number: <u>123-43661</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>447891</u> | Type: <u>WELL</u> | API Number: <u>123-43662</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |

COGCC Comments

| Comment | User | Date |
|---|-----------|------------|
| Refer to attached inspection photos in Document #682401860. | binschusc | 03/15/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 682401860 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099440 |