



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the western portion of the project area from the southwestern corner facing northward. Revegetation is progressing with western wheatgrass (*Pascopyrum smithii*) and intermediate wheatgrass (*Thinorpyum intermedium*). What appears to be surface owner equipment stored in the northwestern portion of the project area.



Photo 3: View of the eastern portion of the project area from the southeastern corner facing northward.



Photo 4: View of debris and stored materials in the northeastern portion of the project area.



Photo 4: View of erosional channel in the northeastern portion of the project area that needs stabilization.