



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward.



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of the southern edge of the well pad that is adjacent to an erosional cut-bank.



Photo 5: View of pipe in the eastern portion of the project area.



Photo 6: View of junk in the eastern portion of the project area.



Photo 7: View of what appears to be surface owner debris in the northeastern portion of the project area.