

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2017

Submitted Date:

03/10/2017

Document Number:

681700361**FIELD INSPECTION FORM**Loc ID 320436 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Brandy	303-339-8600	bsmith@hrmresoures.net	<a href="#">303-893-6621</a>
Pape, Terry	970-768-5700	tpape@hrmres.com	<a href="#">All Inspections</a>
Prohaska, April	303-893-6621	aprohaska@hrmres.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203753	WELL	PR	04/18/1995	OW	001-09313	HSR-CUNNINGHAM 7-10	EI

**General Comment:**[COGCC Environmental Inspection of Tank Battery only.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tank lacking capacity label (see photo)		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	04/09/2017
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	barbed wire fence		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbed wire fence		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Animal burrow observed on north side of separator (inside of berm--see photo).		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	OTHER	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition		
-----------	--	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		Adequate
Comment:	Earthen berm shared with produced water tank.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
-----------	--

Other (Content)	
Other (Capacity)	75 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		Adequate
Comment:	Earthen berm shared with crude oil tank.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 203753 Type: WELL API Number: 001-09313 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401230812	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095872">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095872</a>
681700389	battery sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095848">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095848</a>
681700390	tank battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095849">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095849</a>
681700391	crude oil tank capacity is unclear	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095850">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095850</a>
681700392	separator and meter run	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095851">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095851</a>
681700393	animal burrow observed on NE side of separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4095852</a>