

# Reclamation and Stormwater Inspection

March 14, 2017

Operator: CRESTONE PEAK RESOURCES  
OPERATING LLC

Location ID: 434554

Weld County, CO

SWSE Section 32 T2N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HWY 52 /32H-O268  
Location ID: 434554



**Photo 1.** Photo taken from the entrance of location off County Road 3 1/4, facing East. Vehicle tracking pad installed.



**Photo 2.** Photo taken from the entrance of location off County Road 3 1/4, facing East. Vehicle tracking pad installed.

Inspection Photos  
Location Name: HWY 52 /32H-O268  
Location ID: 434554



**Photo 3.** Photo taken from the entrance of the well site, facing East. Vegetative growth makes it difficult to observe but a ditch and berm BMP has been installed around the perimeter of the location.



**Photo 4.** Photo taken from the northeastern location, facing South. The northeast fill slope has a stabilized outlet that is directed to the ditch and berm BMP.

Inspection Photos  
Location Name: HWY 52 /32H-O268  
Location ID: 434554



**Photo 5.** Photo taken from the northeast sediment trap, facing Southwest. Stabilized outlet in the form of rip rap has been installed.



**Photo 6.** Photo taken from the northeastern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location. Canada thistle vegetative growth from last year was observed throughout the eastern location.

Inspection Photos  
Location Name: HWY 52 /32H-O268  
Location ID: 434554



**Photo 7.** Photo taken from the eastern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location in conjunction with silt fence. Silt fence is in disrepair and needs maintenance. Canada thistle vegetative growth from last year was observed throughout the eastern location.

**Photo 8.** Photo taken from the eastern location, facing South. A ditch and berm BMP has been installed around the perimeter of the location in conjunction with silt fence. Silt fence is in disrepair and needs maintenance.

Inspection Photos  
Location Name: HWY 52 /32H-O268  
Location ID: 434554



**Photo 9.** Photo taken from the eastern location, facing West. Fill slope has a stabilized outlet that is directed to the ditch and berm BMP.



**Photo 10.** Photo taken from the southeast sediment trap, facing Northwest. Vegetative growth makes it difficult to observe but outlet protection in the form of straw wattles may need maintenance or repair.

Inspection Photos  
Location Name: HWY 52 /32H-O268  
Location ID: 434554



**Photo 11.** Photo taken from the southern location, facing West. Pipeline construction occurring during inspection. A ditch and berm BMP appeared to be installed around the southern of the location but may need additional maintenance from pipeline construction disturbance.



**Photo 12.** Photo taken from the entrance of the well site, facing East. A ditch and berm BMP has been installed around the perimeter of the location.