

Inspection Photos
Location Name: Ball Ranch AC 15-65HN
API: 05-123-35074



Photo 1: Stained soil at exhaust



Photo 2: Stained soil at engine

Inspection Photos
Location Name: Ball Ranch AC 15-65HN
API: 05-123-35074



Photo 3: Stained soil at wellhead



Photo 4: Stained soil at produced water

Inspection Photos
Location Name: Ball Ranch AC 15-65HN
API: 05-123-35074



Photo 5: Stained soil at loadout