

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/08/2017

Submitted Date:

03/13/2017

Document Number:

685302366

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
333079 _____ St John, William (Cal) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8455
 Name of Operator: BIG RUN PRODUCTION COMPANY
 Address: 318 WEST RUSK
 City: TYLER State: TX Zip: 75701

Findings:

- 27 Number of Comments
9 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pickard, Joan	(800) 256-2990	elirebichoil@suddenlinkmail.com	All Inspections
Guffey, Ken	970-883-2314	croudine@centurytel.net	Pumper

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205173	WELL	PR	12/01/2015	GW	007-06049	ARGENTA FEE 18	PR
205217	WELL	PR	12/01/2015	GW	007-06094	ARGENTA-FEE 19	PR

General Comment:

See link at end of report for path to downloadable pictures. Any corrective actions from previous inspections are still applicable. Inspection report contains corrective actions and comments. See Good Housekeeping, Equipment, and Related Facility sections of report for additional details.

Location			
Lease Road:			
Type	Access		
comment:	Dirt two track road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing signs located at each wellhead.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tanks labeled.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator contact information on each wellhead.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dried weeds and wire fencing inside stock panels of the Argenta 18.		
Corrective Action:	Remove debris to comply with Rule 603.f using the Rule 603.f guidance document for additional details.		Date: <u>04/13/2017</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused and disconnected equipment inside fenced production equipment area. Valves, fittings, pipe, post with concrete, tank cat walk stairway are all inside the fencing. Similiar issue was noted in previous inspection.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for additional details.		Date: <u>04/13/2017</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused and disconnected produced water tanks inside fenced production equipment area. Similiar issue was noted in previous inspection.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for additional details.		Date: <u>06/12/2017</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused and disconnected equipment at Argent 19 wellhead. Similiar issue was noted in previous inspection.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for additional details.		Date: <u>04/13/2017</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused and disconnected equipment at Argenta Fee 18 wellhead. Similiar issue was noted in previous inspection.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for additional details.		Date: <u>04/13/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:	Post and hog wire fencing with 2 stands of barbwire - Includes gas meter run.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Safety rails.		
Corrective Action:		Date:	

Equipment:

Type	Count	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 5	Comment: Deadmen not marked.	Corrective Action: Locate and mark all deadmen to comply with Rule 1003.a.	Date: 03/29/2017	
Type: Flow Line	# 2	Comment:	Corrective Action:	Date:	
Type: Ancillary equipment	# 1	Comment: Telemetry Equipment.	Corrective Action:	Date:	
Type: Gas Meter Run	# 2	Comment:	Corrective Action:	Date:	
Type: Other	# 3	Comment: Chemical Tank and pump on spill prevention.	Corrective Action:	Date:	
Type: Prime Mover	# 1	Comment: Natural gas motor.	Corrective Action:	Date:	
Type: Ancillary equipment	# 1	Comment: Lube oil tank on spill prevention.	Corrective Action:	Date:	
Type: Pump Jack	# 1	Comment:	Corrective Action:	Date:	
Type: Bird Protectors	# 1	Comment: Heat stack for the separator closest to the wellheads does not have bird protector on heat stack.	Corrective Action: Install wildlife screen to comply with Rule 605.b.(7).	Date: 04/13/2017	
Type: Ancillary equipment	# 2	Comment: Wellhead.			

Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	500 BBLs	STEEL AST		
Comment:	Two disconnected labeled not in use tanks. One is inside production equipment fencing and the other is just outside fencing.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 205173 Type: WELL API Number: 007-06049 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - Electronic well file record review reflects last reported production as December 2015.](#)

Corrective Action: [Report well production via Form 7 as required to comply with Rule 206.](#)

Date: 04/13/2017

Facility ID: 205217 Type: WELL API Number: 007-06094 Status: PR Insp. Status: PR

Producing Well

Comment: [PR - Electronic well file records review reflects last reported production as December 2015.](#)

Corrective Action: [Report well production via Form 7 as required to comply with Rule 206.](#)

Date: 04/13/2017

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Surface area of location and fill slopes are cattle tracked. Location is heavily used by cattle as landowner is using location as a feeding station. All production equipment is fenced.

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? Pass

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? Pass

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Chemical tanks on spill prevention.

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401231780	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096856
685302379	Unused equipment at Argenta 19.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096825
685302380	Debris at Argenta 18.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096826
685302381	Unused equipment at Argenta 18.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096827
685302383	Unused equipment inside production equipment fencing.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096828
685302384	Steel post with concrete inside equipment fencing.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096829
685302385	Disconnected and unused tank 1.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096830
685302386	Disconnected and unused tank 2.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096831
685302387	Feed station on location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096832