

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/09/2017

Submitted Date:

03/13/2017

Document Number:

685302367**FIELD INSPECTION FORM**Loc ID 333956 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**34 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Brock, Christine		Christine.Brock@conocophillips.com	<a href="#">SW Inspection Reports</a>
Prasanna, Sonu	832-486-2299	Sonu.Prasanna@conocophillips.com	<a href="#">SW Inspection Reports</a>
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	<a href="#">SW Inspection Reports</a>
Walker, Crystal	505-326-9837	Crystal.Walker@cop.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258698	WELL	PR	02/22/2007	GW	067-08373	ALLISON UNIT COM 63	PR
258699	WELL	PR	02/22/2007	GW	067-08374	ALLISON UNIT COM 138	PR

**General Comment:**

See link at end of report for path to downloadable pictures. Any corrective actions from previous inspections are still applicable. Inspection report contains corrective actions and comments. See Signs/Marker, Good Housekeeping and Equipment sections of report for additional details.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt two track road. Road is rutted/muddy and will require maintenance as weather permits.		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Open top tank beside the 500 BBL tanks has no sign or labels.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	05/13/2017
Type	TANK LABELS/PLACARDS		
Comment:	500 BBL tank capacity labels are faded and nearly unreadable and the NFPA labels are peeling and need replacement.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs located at produced water tank fencing.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Disconnected valve and parts on the ground around wellhead and pumping unit.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for further detail.	Date:	04/13/2017
Type	OTHER		
Comment:	Stained soil under the bottom of Separator for Allison Unity Com #63. Similiar issue noted in previous inspection.		
Corrective Action:	Clean-up and remediate soil to comply with Rule 906.a.	Date:	04/13/2017
Type	OTHER		
Comment:	Stained soil outside compressor entry way. Less than 5 gallon bucket clean-up.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stained soil around pump jack wellhead. Fluid released from packing.		
Corrective Action:	Clean-up and remediate soil to comply with Rule 906.a	Date:	04/13/2017

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Post and hog wire fencing.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Steel post and pole.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panels.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Post and wire fencing.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Safety rails.		
Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:	Not all deadmen marked.		
Corrective Action:	Locate and mark all deadmen to comply with Rule 1003.a.	Date:	03/29/2017
Type: Ancillary equipment	# 1		
Comment:	Electrical service equipment.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Steel building for compressor.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Lube oil tank with spill prevention. (Compressor)		

Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Riser and valve.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry Equipment.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Wellhead.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment:	Open top tank with steel mesh top for the Allison Unit Com 138.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	No label
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,

Comment:	Open top tank with steel mesh top for the Allison Unit Com #63 well. Tank is steaked and rusting and requires paint.	
Corrective Action:	Paint tank to comply with Rule 804.	Date: 06/12/2017

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	95 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	HEATED STEEL AST		,
Comment:	Above ground heated 500 BBL steel tanks.				
Corrective Action:					
Date:					

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO
Comment:	
Corrective Action:	
Date:	

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

**Inspected Facilities**Facility ID: 258698 Type: WELL API Number: 067-08373 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Electronic well file record review reflects last reported production as June 2016.](#)

Corrective Action:

Date:

Facility ID: 258699 Type: WELL API Number: 067-08374 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Electronic well file record review reflects last reported production as June 2016.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around produced water tanks.

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401231781	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096857">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096857</a>
685302388	Streaked and rusting produced water tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096833">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096833</a>
685302389	Stained soil below Allison Unit Com #63.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096834">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096834</a>
685302390	Produced water tank without sign or labels.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096835">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096835</a>
685302391	Faded capacity label.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096836">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096836</a>
685302392	Stained soil at wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096837</a>
685302393	Unused equipment at wellhead.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096838">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096838</a>
685302394	Stained soil at compressor entry.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096839">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4096839</a>