



Photo 1: View of the project area from the northern corner facing center.



Photo 2: View of the northwestern portion of the project area from the northern corner facing southwestward. Revegetation is heavily grazed as it appears cattle concentrate on the well pad.



Photo 3: View of the northeastern portion of the project area from the northern corner facing southeastward.



Photo 4: View of junk in the northwestern portion of the well pad.



Photo 5: View of the southwestern portion of the project area from the western corner facing southeastward. Old trailer should be removed.



Photo 6: View of erosional channel approximately three feet wide and deep in the southern portion of the project area, flowing into an irrigation canal.



Photo 7: View of the southeastern portion of the project area from the southern corner facing northward.



Photo 8: View of surrounding habitat north of the project area.