

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2017

Submitted Date:

03/15/2017

Document Number:

682401857**FIELD INSPECTION FORM**Loc ID: 449336 Inspector Name: Binschus, Chris On-Site Inspection: ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10311Name of Operator: SYNERGY RESOURCES CORPORATIONAddress: 1675 BROADWAY SUITE 2600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pennington, Dave		dpennington@syrinfo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449564	WELL	DG	03/15/2017		123-44371	Hood 23N-22B-M	CI
449565	WELL	XX	03/08/2017		123-44372	Hood 25C-22-M	CI
449566	WELL	DG	03/16/2017		123-44373	Hood 23C-22-M	CI
449567	WELL	XX	03/08/2017		123-44374	Hood 11N-22C-M	CI
449568	WELL	DG	03/12/2017		123-44375	Hood 14N-22B-M	CI
449569	WELL	DG	03/10/2017		123-44376	Hood 36N-22C-M	CI
449570	WELL	DG	03/11/2017		123-44377	Hood 36C-22-M	CI
449571	WELL	XX	03/08/2017		123-44378	Hood 11N-22A-M	CI
449572	WELL	XX	03/08/2017		123-44379	Hood 23N-22C-M	CI
449573	WELL	DG	03/14/2017		123-44380	Hood 14N-22A-M	CI
449574	WELL	XX	03/08/2017		123-44381	Hood 11C-22-M	CI

**General Comment:**This is a construction and stormwater inspection in response to Form 42- Notice of construction- Document #401219229**Location Construction**Location ID: 449336 CDP: \_\_\_\_\_

Comment: Topsoil salvaged, stored, and temporarily stabilized along the eastern perimeter of location. Per Rule 1002, topsoil shall be stabilized and protected from degradation due to wind and water erosion. Per Rule 1002, BMPs to prevent weed establishment and to maintain soil microbial activity shall be implemented.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** An area of 8.70 acres was mapped on 3/3/2017 using a Trimble Juno 3B handheld device.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:

**Date:****Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs:

Other BMPs:

Corrective Action:

Date:

BERMS	Yes		
-------	-----	--	--

Comments: Erosion BMPs:

Ensure berm BMPs are consistently compacted throughout location.

Other BMPs:

Corrective Action:

Date:

**Comment:**

BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.

**Corrective  
Action:****Date:****On Site Inspection (305):**Surface Owner Contact Information:

Name:

Address:

Phone Number:

Cell Phone:

Operator Rep. Contact Information:

Landman Name:

Phone Number:

Date Onsite Request Received:

Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name:

Phone Number:

Agreed to Attend:

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: <u>449564</u>	Type: <u>WELL</u>	API Number: <u>123-44371</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449565</u>	Type: <u>WELL</u>	API Number: <u>123-44372</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449566</u>	Type: <u>WELL</u>	API Number: <u>123-44373</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449567</u>	Type: <u>WELL</u>	API Number: <u>123-44374</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449568</u>	Type: <u>WELL</u>	API Number: <u>123-44375</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449569</u>	Type: <u>WELL</u>	API Number: <u>123-44376</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449570</u>	Type: <u>WELL</u>	API Number: <u>123-44377</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449571</u>	Type: <u>WELL</u>	API Number: <u>123-44378</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449572</u>	Type: <u>WELL</u>	API Number: <u>123-44379</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449573</u>	Type: <u>WELL</u>	API Number: <u>123-44380</u>	Status: <u>DG</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449574</u>	Type: <u>WELL</u>	API Number: <u>123-44381</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401858.</a>	binschusc	03/15/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401234787	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099676">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099676</a>
682401858	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099439">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099439</a>