

Construction and Stormwater Inspection

March 21, 2017

Operator: WARD PETROLEUM CORPORATION-
#10359

Location ID: 440718

Adams County, CO

SWSE Section 24 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Schaefer /24-3-7HC
Location ID: 440718



Photo 1. Photo taken from the entrance location, facing East. Two (2) sets of culverts installed in conjunction with existing ditches. Gravel installed at entrance of location.



Photo 2. Photo taken from the entrance location, facing West. Two (2) sets of culverts installed in conjunction with existing ditches. Gravel installed at entrance of location.

Inspection Photos
Location Name: Schaefer /24-3-7HC
Location ID: 440718



Photo 3. Photo taken from the southwest location, facing East. A ditch and berm BMP has been installed around the perimeter of location. Berm does not appear to be consistently compacted. Topsoil stockpile salvaged and stored along the southern location and along a portion of the southeastern location.



Photo 4. Photo taken from the southeastern location, facing North. A ditch and berm BMP has been installed around the perimeter of location. Berm does not appear to be consistently compacted and vehicle traffic should stay off BMPs to ensure they properly function.

Inspection Photos
Location Name: Schaefer /24-3-7HC
Location ID: 440718



Photo 5. Photo taken from the southeastern location, facing North, of the southeastern topsoil stockpile.



Photo 6. Photo taken from the eastern location, facing North. A ditch and berm BMP has been installed around the perimeter of location. Berm does not appear to be consistently compacted.

Inspection Photos
Location Name: Schaefer /24-3-7HC
Location ID: 440718



Photo 7. Photo taken from the northern location, facing West. A ditch and berm BMP has been installed around the perimeter of location. Berm does not appear to be consistently compacted.



Photo 8. Photo taken from the northwest location, facing South. A ditch and berm BMP has been installed around the perimeter of location. Berm does not appear to be consistently compacted.