

## Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



**Photo 1: Weeds in tank battery**



**Photo 2: Stained soil at fitting**



## Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



**Photo 3: Stained soil beneath scrubber**



**Photo 4: Stained soil at fitting**



**Inspection Photos**  
**Location Name: Spaur Brothers North Pad 31-219HN**  
**API: 05-123-38693**



**Photo 5: Weeds at ECDs**



**Photo 6: Stained soil at compressor**

## Inspection Photos

Location Name: Spaur Brothers North Pad 31-219HN

API: 05-123-38693



**Photo 1: Stained soil in cellar of Spaur Bros EH 31-259HC.  
Grate made photograph difficult.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources