

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/10/2017

Submitted Date:

03/16/2017

Document Number:

678200634

FIELD INSPECTION FORM

Loc ID 317349 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 24320
Name of Operator: DIAMOND OPERATING, INC.
Address: 6666 GUNPARK DR STE #200
City: BOULDER State: CO Zip: 80301

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Peterson, Dave	(303) 494-4420	davep@flatironenergy.com	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
104604	PIT				-	WARD 4	EI
104605	PIT				-	WARD 4	EI
117678	PIT				-	WARD	EI

General Comment:

Environmental inspection related to Rem #8428.
Operator has provided documents related to Rem #8428 as requested via telephone conversation. Based on the information provided and the conditions observed during this inspection, Rem #8428 will be closed.
Operator has agreed to develop a more robust method of containing potential emulsion carryover from the skimming tanks.

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 104605 Lat: 39.900897 Long: -103.405185

Reference Point: _____ Other: _____ Length: 65 Width: 70

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Square, small central pit, skim tank outfall.

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

Type: Produced Water Lined: NO Pit ID: 117678 Lat: 39.900897 Long: -103.405185

Reference Point: _____ Other: _____ Length: 150 Width: 60

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Narrow triangular pit on the west side of the location.

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		
Corrective Action		Date:
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID: <u>104604</u>
Lat: <u>39.900897</u>	Long: <u>-103.405185</u>	
Reference Point: _____	Other: _____	Length: <u>220</u> Width: <u>180</u>
Lining:		
Liner Type:	Liner Condition:	
Comment:	<u>Large produced water pit on the east side of the location, surface discharge location.</u>	
Corrective Action		Date: <u>g</u>
Fencing:		
Fencing Type:	Fencing Condition:	
Comment:		
Corrective Action		Date:
Netting:		
Netting Type:	Netting Condition:	
Comment:		
Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		
Corrective Action		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401235638	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4100669
678200643	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4100668