

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2017

Submitted Date:

03/23/2017

Document Number:

674901539**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 76104Name of Operator: SAMSON RESOURCES COMPANYAddress: 15 E 5TH ST STE 1000City: TULSA State: OK Zip: 74103**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Blanchard, Johnna	970-884-5085	jblanchard@samson.com	All SW Inspections
Ikenouye, Teri		teri.ikenouye@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

General Comment:

On March 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Samson Resources Pit Facility ID #115680. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115680 shall be administratively closed in the COGIS database after desktop review and this field inspection.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Type: Lined: Pit ID: 115680 Lat: 37.051291 Long: -107.629850

Reference Point: Other: Length: Width:

Lining:Liner Type: Liner Condition: Comment: Location inspection conducted to determine physical existence of pit facility ID #115680.Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
On March 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Samson Resources Pit Facility ID #115680. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115680 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pit.	hughesj	03/23/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901540	Schofield Auto 31X #5-2 pump jack.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106609
674901541	067-07488 well head. No surface indication of pit.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106610